DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/Ala Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-007184 Address: 333 Burma Road **Date Inspected:** 20-May-2009

City: Oakland, CA 94607

OSM Arrival Time: 1845 **Project Name:** SAS Superstructure **OSM Departure Time:** 645 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes No Li Ming, Wan Wen Zhong **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Tower Components

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector George Goulet was present during the times noted above for observations relative to the work being performed.

Bay 10

This QA Inspector, George Goulet, randomly observed the following work in progress in Bay 10:

SAW welding of weld joint NSD1-FCSA4-1A/C-61A located on PCMK north tower, lift 4, skin C. Welder was identified as 040252. ZPMC QC was identified as CWI Liu Yang (QC1). Assisting QC1 at this location and appearing to be monitoring the welding and recording data was ZPMC QC Inspector Shi Jing Wei, who was not a CWI. The welding variables recorded by QC1 and his assistant appeared to comply with WPS-B-T-2221-B-U3c-S-2.

SAW welding of weld joint NSD1-FCSA4-1A/C-58 located on PCMK north tower, lift 4, skin C. Welder was identified as 050295. ZPMC QC was identified as QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was ZPMC QC Inspector Shi Jing Wei, who was not a CWI. The welding variables recorded by QC1 and his assistant appeared to comply with WPS-B-T-2221-B-P3-S-2.

SAW welding of weld joint NSD1-FCSA4-1A/C-19A located on PCMK north tower, lift 4, skin C. Welder was identified as 051413. ZPMC QC was identified as QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was ZPMC QC Inspector Shi Jing Wei, who was not a CWI. The welding variables recorded by QC1 and his assistant appeared to comply with WPS-B-T-2221-B-U3c-S-2.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

FCAW welding of weld joint NSD1-FASA3-1E/E-45-A located on PCMK north tower, lift 3, skin A which was mounted on an A-frame. Welders were identified as 053869. ZPMC QC was identified as QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was ZPMC QC Inspector Sun Tian Liang, who was not a CWI. The welding variables recorded by QC1 and his assistant appeared to comply with WPS-345-FCAW-1G(1F)-repair.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

As noted above, and this QA Inspector, George Goulet, asked each QC if all the welding variables observed by him appeared to comply with the appropriate WPS, including the preheat requirements according to thickness of the thickest member being welded. Each QC showed this QA Inspector, George Goulet, that he was carrying the proper temperature sticks to monitor the minimum and maximum preheat and interpass temperatures and replied that all he observed did appear to comply.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod, 134-8257-0045, who represents the Office of Structural Materials for your project.

Inspected By:	Goulet,George	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer